



GO BEYOND

ENGINEWISE

HPT STAGE-2 RING SEGMENT & VANE CLUSTER FULL OVERHAUL FOR POST SB72-0649 PN

The V2500-A1/A5/D5 HPT Stage-2 Ring Segment & Vane Cluster now includes four new (POST-SB 72-0649) part numbers into the full overhaul capability list. The repairs developed cover the following:

- Strip & Recoat
- Crack Repairs
- Cooling Hole Repair
- Honeycomb Repair
- Airflow Inspection
- Vane Cluster Assembly

SPECIFICS

P&W Engine Manual Ref: [PN 2A4407](#)

Model: [V2500 A1/A5/D5](#)

ATA#: [72-45-24](#)

SB Ref: [SB72-0649](#)

AVAILABILITY

Repair is applicable for the following part numbers:

2A4462 2A4482

2A4562 2A4582


BENEFITS

Increased reparability of the vane

Optimizes part life

Reduces total cost of ownership

PART REFERENCE



Typical V2500 HPT Stage-2 Vane Assembly

Turbine Overhaul Services Pte Ltd
No. 5 Tuas Drive 2 Singapore 638639

Cheah Kim Wei - Sales Manager
Mobile: +65-9699 9298
Email: kim.wei.cheah@prattwhitney.com