



GO BEYOND

ENGINEWISE

## No. 4 BEARING SCAVENGE OIL TUBE ASSEMBLY HEAT SHIELD REPLACEMENT REPAIR

The new V2500-A1/A5 No. 4 Bearing Scavenge Oil Tube Assembly Heat Shield Replacement Repair developed by Pratt & Whitney restores damaged heat shields and provides the customer an alternative to new part assembly replacement, producing an estimated repair yield of 90%, optimizing the part life cycle and reducing the total cost of ownership.

### SPECIFICS

P&W Engine Manual Ref: [THD-V2500-11A & THD-V2500-31A, VRS3832](#)  
Model: [V2500-A1/A5/ D5](#)  
ATA#: [72-42-20](#)  
SB Ref: [SB ENG-72-0650](#)

### AVAILABILITY

CAS is licensed to perform this proprietary repair.  
The repair is available from 15-Oct 2018 and will be applicable for the following part number:  
2A4379-01

### BENEFITS

Optimizes the part life cycle  
Reduces total cost of ownership  
Estimated repair yield of 90%

### PART REFERENCE





Figure 1: Location of No. 4 Bearing Scavenge Oil Tube Assembly



No. 4 Bearing Scavenge Oil Tube Assembly

Figure 2: Heat Shield Replacement Repair

Component Aerospace Singapore (CAS)  
10 Loyang Lane; Singapore 508916

Ivan Wan - Aftermarket Sales Manager  
Tel: +886 2 27190395 / Mobile +886 933 923963  
Email: [ivan.wan@prattwhitney.com](mailto:ivan.wan@prattwhitney.com)