



GO BEYOND

ENGINEWISE

V2500 UNISON SYNC RING STAGE 3, 4, 5, VIGV

Pratt & Whitney has developed new repair capabilities for the V2500-A1/A5/D5 High Pressure Compressor (HPC) Unison Sync Ring. The new repair capabilities bring the unison sync ring body back to serviceability, leading to a reduction in part scrappage and a lower total cost of ownership.

SPECIFICS

P&W Engine Manual Ref: [E-V2500-11A](#)


[E-V2500-31A](#)

Model: [6A7888](#), [6A7890](#), [6A7984](#),
[6A7896](#), [6A7899](#), [6A7901](#), [6A7903](#),
[6A7906](#), [6A8075](#), [6A8077](#)

ATA#: [72-41-34](#)

SB Ref: [V2500-ENG-72-0418](#)

PART REFERENCE



AVAILABILITY

Rivet Crack Weld Repair (VRS6544)

Helicoil Repair (VRS6155, VRS6156)

Surface Blend Repair (VRS6186, VRS6158, VRS6159, VRS6195)

Replacement Repair (VRS6247, VRS6246, VRS6248, VRS6265)

BENEFITS

Reduces total cost of ownership

Increases part lifecycle

Component Aerospace Singapore (CAS)
10 Loyang Lane, Singapore 508916

Ivan Wan - Aftermarket Sales Manager
Tel: +886 2 27190395 / Mobile: +886 933 923963
Email: ivan.wan@prattwhitney.com